

## Guitar Hero Service Bulletin

**Date:** 2/26/09

**To:** Service and Parts Managers

**Reason:** Software Version 0.3.9 and Hardware Update

**Games Affected:** S/N 1022,1023,1026,1027,1028,1029,1030 & 1041

Raw Thrills Engineers have made some changes to the Guitar Hero games. You will receive today 2 fret covers, 1 restore disk 0.3.9 and 1 operators manual.

Please remove the existing fret cover and replace with the one provided and run the updated software restore disk.

If you have any questions please contact me.

Thank you

George Angermeyer

Betson Enterprises

201-438-1300 x3331

Gangermeyer@Betson.com

